

PARTS

A



1PC

B




1PC

C




4PCS

1



2



Do not overtighten.
Do not use power tools to assemble.

TOC20261014